



选择5V供电时，R5、R17
不焊，R6焊0R，R11焊0R
3.3V供电时，R5焊0R，R6
不焊，R11焊24K，R17焊47
K。

Title			DebugDump.com USB转RS485		
Size	Number		Revision		
A4					
Date:	2018/10/27		Sheet of		
File:	D:\Documents\...\USB&RS485 V1.SchDoc		Drawn By:		